



Cross Reference RA Part Number PN-317992

Operator's Manual

12. Order information

12.1. REA 10_ units

Table 12.1.-1 Order numbers

Arc protection relay REA 101 U _n = 110...240 V AC U _n = 110...250 V DC	REA101-AAA ^a
Arc protection relay REA 101 U _n = 24...60 V DC	REA101-CAA ^a
Arc protection relay REA 101 with optolink connectors for glass fiber U _n = 110...240 V AC U _n = 110...250 V DC	REA101-AAAG ^a
Arc protection relay REA 101 with optolink connectors for glass fiber U _n = 24...60 V DC	REA101-CAAG ^a
Rear plate protective cover	1MRS 060196
Mounting kit for semi-flush mounting	1MRS 050254
Mounting kit for surface mounting	1MRS 050240
Mounting kit for connecting cases together	1MRS 050241
Mounting kit for 19" rack	1MRS 050258
Extension unit REA 103	REA103-AA
Extension unit REA 105	REA105-AA
Extension unit REA 107	REA 107-AA

a. Includes mounting kit 1MRS 050209 for flush mounting.

12.2. Fiber sensors

Table 12.2.-1 Pre-manufactured fiber sensors

Length	Order number
5 m ±3%	1MRS 120512.005
10 m ±3%	1MRS 120512.010
15 m ±3%	1MRS 120512.015
20 m ±3%	1MRS 120512.020
25 m ±3%	1MRS 120512.025
30 m ±3%	1MRS 120512.030
40 m ±3%	1MRS 120512.040
50 m ±3%	1MRS 120512.050
60 m ±3%	1MRS 120512.060

Table 12.2.-2 Accessories for manufacturing fiber sensors

Sensor fiber 100 m	1MSC 380018.100
Sensor fiber 300 m	1MSC 380018.300
Sensor fiber 500 m	1MSC 380018.500
ST connector	SYJ-ZBC 1A1
ST splice adapter	SYJ-ZBC 1A2
ST fiber termination kit	1MSC 990016